


- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo  
Not Available



After Photo  
Not Available

**Site Name:** NATOMAS BENNETT PLANT

**Stream Name:** Cross Canal

**Structure Owner:** Natomas Central Mutual Water Co.

**Year Remediated:** 2012

**Site Type:** Diversion

**Site Status After Remediation:** Not a barrier

**Species Benefited After Remediation:** Unknown

**Immediate Downstream barrier PAD ID:**

**PAD ID:** [702866](#)

**Tributary To:** Sacramento River

**Barrier Remediation By:** U.S. Fish and Wildlife Service

**Barrier Description Prior to Remediation:** Unscreened

**Count of Barriers Downstream:**

**Count of Barriers Upstream:**

**Distance Upstream to Next Barrier or Limit of Anadromy :**                      mi

\*Site statistics based on December 2014 version of the Passage Assessment Database

**Notes:** This was an unscreened diversion per a field survey in 1994 assessed by CDFW. In November 2012, the Bolen, Northern, and Bennett diversions on the Natomas Cross Canal was removed and replaced with a consolidated screened diversion on the Sacramento River at Sankey (PAD ID 758606). At the same time the diversion structure at this location was removed except for the concrete foundations which were left in place to avoid adverse habitat impacts.