


- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo
Not Available



After Photo
Not Available

Site Name: Bike Trail Crossing

Stream Name: San Antonio Creek

Structure Owner: Ventura County Parks

Year Remediated: 2012

Site Type: Road crossing

Site Status After Remediation: Remediated, fish response unconfirmed

Species Benefited After Remediation: Unknown

Immediate Downstream barrier PAD ID:

Notes: Barrier was removed and replaced by a steel truss bridge. Before: low flow crossing, concrete box culverts. This was a temporal barrier per professional judgement by Entrix, Incorporated. The original crossing consisted of reinforced concrete culvert structure with four passages each about 2 feet tall and 3 feet wide.

PAD ID: 713866

Tributary To: Ventura River

Barrier Remediation By: Unknown

Barrier Description Prior to Remediation: Temporal

Count of Barriers Downstream:

Count of Barriers Upstream:

Distance Upstream to Next Barrier or Limit of Anadromy : mi

*Site statistics based on December 2014 version of the Passage Assessment Database