



- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo
Not Available



Site Name: Quimby Island

Stream Name: Old River

Structure Owner: Unknown

Year Remediated: 2012

Site Type: Diversion

Site Status After Remediation: Screened

Species Benefited After Remediation: Unknown

Immediate Downstream barrier PAD ID:

Notes: DELTA RESURVEY FEB2005. Before: Unscreened diversion per field survey by CDFG.

PAD ID: 717666

Tributary To: San Joaquin River

Barrier Remediation By: Unknown

Barrier Description Prior to Remediation: Unscreened

Count of Barriers Downstream:

Count of Barriers Upstream:

Distance Upstream to Next Barrier or Limit of Anadromy : mi

*Site statistics based on December 2014 version of the Passage Assessment Database