



- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ☆ Unscreened Diversion
- Unknown Passage Status
- Unassessed



Site Name: Payness Crossing (Middle Slab)

Stream Name: Antelope Creek

Structure Owner: Unknown

Year Remediated: 2012

Site Type: Road crossing

Site Status After Remediation: Remediated, fish response unconfirmed

Species Benefited After Remediation: Unknown

Immediate Downstream barrier PAD ID:

PAD ID: 757955

Tributary To: Sacramento River

Barrier Remediation By: Unknown

Barrier Description Prior to Remediation: Temporal

Count of Barriers Downstream:

Count of Barriers Upstream:

Distance Upstream to Next Barrier or Limit of Anadromy : mi

*Site statistics based on December 2014 version of the Passage Assessment Database

Notes: The low water crossing was a barrier to fish passage and was replaced with a bridge. CDFW staff conducted a post-removal snorkel survey. One fish was observed downstream of the barrier, just hanging out. Another snorkel survey will be conducted in summer 2013. Before: Temporal barrier per professional judgement by USFWS. Passage impediment during springs when there is low flow.