

TABLE OF CONTENTS

VOLUME 1

Section	Page
SUMMARY	i
ACRONYMS/ABBREVIATIONS	xxix
1 INTRODUCTION	
1.1 Purpose	1-1
1.2 Scope	1-1
1.3 Responses to Regulatory and Community Review	1-3
2 BACKGROUND	
2.1 Description	2-1
2.2 History - SSTB	2-1
2.2.1 World War II Era	2-2
2.2.1.1 U.S. Navy Operations	2-2
2.2.1.2 Aeroballistic Testing	2-2
2.2.2 Post-World War II Transfer and Base Renovation	2-3
2.2.2.1 Base Transfer	2-3
2.2.2.2 Renovation	2-3
2.2.3 Aeroballistic Testing	2-4
2.2.4 Natural Environmental Test Program	2-5
2.2.5 Project Mercury Testing	2-5
2.2.6 Aeroballistic Test Unit Recovery	2-5
2.2.7 Navy Reacquisition	2-5
2.3 Previous and Ongoing Investigations	2-6
2.3.1 Preliminary Assessment	2-6
2.3.2 Electrical System Decommissioning	2-7
2.3.3 Asbestos Abatement	2-7
2.3.4 Fuel Storage Tank Investigations	2-7
3 ENVIRONMENTAL SETTING	
3.1 Regional Setting and Topography *...**...*...*.....	3-1

TABLE OF CONTENTS (continued)

Section	Page
3.2	Climate 3-1
3.3	Regional Geology 3-1
3.4	Hydrogeology 3-2
3.5	Regional Hydrology 3-3
3.5.1	Salton Sea Water Level 3-4
3.5.2	Salton Sea Water Chemistry 3-4
3.5.2.1	Salinity 3-4
3.5.2.2	Water Temperature 3-5
3.5.2.3	Oxygen Concentration 3-5
3.5.2.4	Biological Contamination 3-5
3.5.2.5	Chemical Contamination 3-5
3.6	Population Density 3-6
3.7	Ecological Features 3-7
3.7.1	Vegetation 3-7
3.7.1.1	Human-Planted and Disturbed Vegetation 3-7
3.7.1.2	Sonoran Desert Vegetation 3-8
3.7.1.3	Shoreline Vegetation 3-8
3.7.1.4	Aquatic Vegetation 3-9
3.7.2	Wildlife 3-9
3.7.2.1	Amphibians and Reptiles 3-9
3.7.2.2	Birds 3-9
3.7.2.3	Mammals 3-10
3.7.2.4	Aquatic Wildlife 3-10
3.7.3	Summary 3-10
4	SI APPROACH AND RATIONALE
4.1	Statement of Problem 4-1
4.2	Identification of Decisions 4-1
4.3	Identification of Decision Inputs 4-2
4.4	Study Boundaries 4-2
4.5	Decision Rules 4-2
4.6	Limits on Decision Error 4-3
4.7	Sampling Design 4-3

TABLE OF CONTENTS (continued)

Section		Page
4.7.1	Feature Location and Delineation	4-4
4.7.2	Surveying	4-4
4.7.3	Contaminant Characterization	4-4
	4.7.3.1 Sampling Rationale	4-4
	4.7.3.2 Selection of Analytical Methodologies	4-5
4.7.4	Contaminant Fate and Transport Parameter Characterization.....	4-5
4.7.5	Risk Screening	4-5
4.7.6	Standards for Data Quality	4-6
5 SI METHODOLOGIES		
5.1	Field Activities	5-1
5.1.1	Topographic Mapping	5-1
5.1.2	Land Geophysical Surveys..	5-2
	5.1.2.1 Electromagnetic Induction	5-2
	5.1.2.2 Magnetometry	5-3
	5.1.2.3 Ground Penetrating Radar	5-3
	5.1.2.4 Metal Detector	5-4
	5.1.2.5 Calibration	5-4
	5.1.2.6 Data Interpretation	5-5
5.1.3	Marine Geophysical Surveys	5-6
	5.1.3.1 Side Scan Sonar	5-6
	5.1.3.2 Bathymetry	5-7
	5.1.3.3 Sub-Bottom Profiling	5-7
	5.1.3.4 Marine Magnetometry	5-7
	5.1.3.5 Calibration	5-8
	5.1.3.6 Data Interpretation	5-8
5.1.4	Utility Clearance	5-8
5.1.5	Soil Gas Surveys..	5-9
	5.1.5.1 Sample Collection	5-9
	5.1.5.2 Analytical Procedures	5-10
	5.1.5.3 Quality Assurance	5-10
5.1.6	Soil Sampling	5-11
	5.1.6.1 Drilling	5-11
	5.1.6.2 Test Pits	5-12
	5.1.6.3 Hand Auger and Surficial Grab Sampling..	5-13
5.1.7	Monitoring Well Installation	5-14

TABLE OF CONTENTS (continued)

Section	Page	
5.1.8	Monitoring Well Development	5-15
5.1.9	Groundwater Sampling	5-16
5.1.10	Aquifer Testing	5-17
5.1.10.1	Field Methodology	5-17
5.1.10.2	Data Analysis	5-18
5.1.10.3	Results	5-20
5.1.11	Sediment Sampling	5-20
5.1.12	Surface Water Sampling	5-21
5.1.13	Field Screening	5-22
5.1.13.1	Headspace Survey	5-22
5.1.13.2	Radiological Survey	5-22
5.1.14	Decontamination Procedures	5-23
5.1.15	Sample Quality Assurance Procedures	5-23
5.1.15.1	Field Duplicates	5-24
5.1.15.2	Field Blanks	5-24
5.1.16	Health and Safety Procedures	5-25
5.1.16.1	Potential Contaminants of Concern	5-25
5.1.16.2	Hazardous Work Permits	5-25
5.1.16.3	Personal Protective Equipment	5-25
5.1.16.4	Radiological Surveillance	5-26
5.1.16.5	Air Monitoring	5-26
5.1.16.6	Contamination Control	5-26
5.1.16.7	Respiratory Protection	5-27
5.1.16.8	Dosimetry	5-27
5.1.16.9	Work Over Water	5-27
5.1.16.10	Training Program	5-27
5.1.16.11	Unusual Incidents	5-28
5.1.17	Investigation-Derived Waste Management	5-28
5.1.18	Surveying and Positioning	5-29
5.1.18.1	Marine Geophysics	5-29
5.1.18.2	Sediment/Surface Water Samples	5-30
5.1.18.3	Land Surveying	5-30
5.1.19	Field Documentation	5-31
5.1.19.1	Sample Station Identification	5-31
5.1.19.2	Analytical Sample Identification	5-31
5.1.19.3	Field Records	5-32

TABLE OF CONTENTS (continued)

Section	Page	
5.2	Chemical Analysis.....	5-32
5.2.1	Analytical Procedures.....	5-32
5.2.2	Detection Limits	5-34
5.2.2.1	Soil and Sediment Samples	5-34
5.2.2.2	Groundwater Samples	5-35
5.2.2.3	Surface Water Samples	5-35
5.2.2.4	Elevated Detection Limits	5-36
5.2.3	Analytical Quality Assurance.....	5-38
5.2.3.1	Certification	5-38
5.2.3.2	Field Duplicates	5-38
5.2.3.3	Field Blanks	5-38
5.2.3.4	Trip Blanks	5-39
5.2.4	Laboratory Quality Control Analyses	5-40
5.2.5	Data Validation.....	5-41
5.3	Data Evaluation - Laboratory Contaminants	5-41
5.3.1	Evaluation Criteria	5-42
5.3.2	Evaluation of Laboratory Contaminants for Risk Screening	5-42
5.3.3	Volatile Organic Compounds	5-43
5.3.3.1	2-Butanone	5-43
5.3.3.2	Acetone	5-43
5.3.3.3	Methylene Chloride	5-43
5.3.3.4	Toluene	5-43
5.3.4	Semi-Volatile Organic Compounds	5-43
5.3.4.1	Bis(2-Ethylhexyl)Phthalate	5-44
5.3.4.2	Butylbenzylphthalate	5-44
5.3.4.3	Di-N-Butylphthalate	5-45
5.3.4.4	Diethylphthalate	5-45
5.3.4.5	Di-N-Octylphthalate	5-45
5.3.4.6	Tentatively Identified Compounds	5-45
5.3.5	Data Evaluation - Tentatively Identified Compounds	5-46
5.4	Geotechnical Analyses	5-46
6	SUMMARY OF RESULTS	
6.1	Base-Wide Conditions	6-1
6.1.1	Geology/Hydrogeology	6-1
6.1.1.1	Sites 1 and 15	6-1
6.1.1.2	Sites 6,7, 11 and 23B	6-2
6.1.1.3	Sites 4, 10 and 12 (Marine)	6-2

TABLE OF CONTENTS (continued)

Section	Page
6.1.1.4	Main Base Area 6-3
6.1.1.5	Sites 4 and 20 6-3
6.1.1.6	Sites 22,23D and 25 6-4
6.1.1.7	Remote Camera Site B-1 6-4
6.1.2	Groundwater Quality 6-4
6.1.3	Hydrology 6-5
6.1.4	Soil Gas 6-5
6.1.5	Field Screening Results 6-6
6.2	Background Characterization 6-6
6.2.1	Background Sampling Locations and Analysis 6-6
6.2.1.1	Soil 6-6
6.2.1.2	Groundwater 6-7
6.2.1.3	Sediment 6-7
6.2.1.4	Surface Water 6-7
6.2.2	Background Characterization Results - Organics 6-7
6.2.2.1	Soil 6-8
6.2.2.2	Groundwater 6-8
6.2.2.3	Sediment 6-9
6.2.2.4	Surface Water 6-9
6.2.3	Background Characterization of Naturally Occurring Compounds . 6-9
6.2.3.1	Statistical Methodology - Upper Tolerance Limits 6- 10
6.2.3.2	Uncertainties in Application of Upper Tolerance Limits 6- 11
6.2.3.3	Discrimination Between Background and Contamination Methodolgy 6-12
6.3	Air Sampling 6-12
6.3.1	Analytical Methods 6-12
6.3.2	Sampling Methodology 6-13
6.3.3	Airborne Asbestos 6-13
6.3.4	Airborne Metals 6-14
6.3.5	Analytical Results 6-14
6.3.6	Summary of Findings 6-15
6.4	Site 1 – Taxiway Landfill 6-15
6.4.1	Site History 6-15
6.4.2	Geophysical Survey 6-16
6.4.3	Soil Gas Survey 6-16
6.4.4	Test Pit Excavation 6-17
6.4.5	Surficial Grab Soil Sampling 6-17
6.4.6	Drilling 6-17
6.4.7	Analytical Results 6-17

TABLE OF CONTENTS (continued)

Section		Page
	6.4.7.1 Soil Samples	6-18
	6.4.7.2 Groundwater Samples	6-20
6.5	Site 4 – Shoreline Disposal Area	6-20
	6.5.1 Site History	6-20
	6.5.2 Geophysical Survey	6-20
	6.5.2.1 Land	6-20
	6.5.2.2 Marine	6-21
	6.5.3 Soil Sampling	6-21
	6.5.4 Sediment Sampling	6-21
	6.5.5 Surface Water Sampling	6-22
	6.5.6 Analytical Results	6-22
	6.5.6.1 Soil Samples	6-22
	6.5.6.2 Sediment Samples	6-22
	6.5.6.3 Surface Water Sample	6-23
6.6	Site 6 – Building 4033 – Instrument Laboratory Leach Line	6-24
	6.6.1 Site History	6-24
	6.6.2 Geophysical Survey	6-24
	6.6.3 Soil Gas Survey	6-25
	6.6.4 Drilling	6-25
	6.6.5 Analytical Results – Soil Sampling	6-25
6.7	Site 7 – Building 4070 – Dog Site Leach Field	6-27
	6.7.1 Site History	6-27
	6.7.2 Geophysical Survey	6-28
	6.7.3 Soil Gas Survey	6-28
	6.7.4 Drilling	6-28
	6.7.5 Analytical Results – Soil Samples	6-29
6.8	Site 8 – Building 4055 – Grease Pit	6-29
	6.8.1 Site History	6-29
	6.8.2 Drilling	6-30
	6.8.3 Analytical Results	6-30
	6.8.3.1 Soil Samples	6-30
	6.8.3.2 Groundwater Samples	6-30
6.9	Site 9 – Buildings 4026, 4027, and 4070 – Radiological Survey	6-31
	6.9.1 Site History	6-31
	6.9.2 Survey Objective	6-31

TABLE OF CONTENTS (continued)

Section	Page
6.9.3 Instrumentation	6-32
6.9.4 Background Determination	6-33
6.9.5 Survey Preparation	6-33
6.9.6 Gamma Exposure Rate Measurements	6-34
6.9.7 Surface Activity Measurements	6-34
6.9.8 Transferable Contamination Measurements	6-35
6.9.9 Summary of Results	6-36
6.10 Site 10 – SSTB Target Ranges	6-36
6.10.1 Site History	6-36
6.10.2 Land Geophysical Survey	6-36
6.10.3 Marine Geophysical Survey	6-37
6.10.4 Sediment Sampling.....	6-37
6.10.5 Surface Water Sampling.....	6-38
6.10.6 Analytical Results	6-38
6.10.6.1 Sediment Samples	6-38
6.10.6.2 Surface Water Samples	6-38
6.11 Site 11 – Building 4033 Landfill	6-38
6.11.1 Site History	6-39
6.11.2 Geophysical Survey	6-39
6.11.3 Soil Gas Survey	6-40
6.11.4 Test Pit Excavation.....	6-40
6.11.5 Analytical Results – Soil Samples	6-40
6.12 Site 12 – East-West Runway Landfill	6-42
6.12.1 Site History	6-42
6.12.2 Geophysical Survey.....	6-43
6.12.2.1 Land	6-43
6.12.2.2 Marine.....	6-43
6.12.3 Sediment Sampling.....	6-44
6.12.4 Surface Water Sampling.....	6-44
6.12.5 Analytical Results	6-44
6.12.5.1 Sediment Samples	6-45
6.12.5.2 Surface Water Samples	6-45
6.13 Site 13 – Gully Landfill	6-45
6.13.1 Site History	6-45
6.13.2 Geophysical Survey.....	6-46

TABLE OF CONTENTS (continued)

Section	Page
6.13.3 Soil Gas Survey	6-46
6.13.4 Test Pit Excavation	6-46
6.13.5 Drilling.....	6-47
6.13.6 Analytical Results	6-47
6.13.6.1 Soil Samples	6-47
6.13.6.2 Groundwater Samples	6-48
6.14 Site 14 - Warehouse Landfill	6-48
6.14.1 Site History	6-48
6.14.2 Geophysical Survey.....	6-49
6.14.3 Soil Gas Survey	6-49
6.14.4 Test Pit Excavation.....	6-49
6.14.5 Drilling.....	6-49
6.14.6 Analytical Results	6-50
6.14.6.1 Soil Samples	6-50
6.14.6.2 Groundwater Samples	6-51
6.15 Site 15 - Building 4049 - Paint Shop	6-51
6.15.1 Site History	6-51
6.15.2 Drilling.....	6-51
6.15.3 Analytical Results.....	6-51
6.15.3.1 Soil Samples	6-51
6.15.3.2 Groundwater Samples	6-52
6.16 Site 16 - Building 4009 - Paint Storage	6-53
6.16.1 Site History	6-53
6.16.2 Drilling.....	6-53
6.16.3 Analytical Results.....	6-53
6.16.3.1 Soil Samples	6-53
6.16.3.2 Groundwater Samples	6-54
6.17 Site 17 - Old Building 5 - Vehicle Maintenance Area	6-54
6.17.1 Site History	6-54
6.17.2 Geophysical Survey.....	6-54
6.17.3 Soil Gas Survey	6-54
6.17.4 Test Pit Excavation.....	6-54
6.17.5 Drilling.....	6-55
6.17.6 Analytical Results.....	6-55

TABLE OF CONTENTS (continued)

Section	Page
6.17.6.1 Soil Samples	6-55
6.17.6.2 Groundwater Samples	6-55
6.18 Site 18 - Old Buildings 3 and 4 - Shops	6-56
6.18.1 Site History	6-56
6.18.2 Drilling	6-56
6.18.3 Analytical Results	6-56
6.18.3.1 Soil Samples	6-57
6.18.3.2 Groundwater Samples	6-57
6.19 Site 19 - Old Buildings 4006,4007,4008,4050 - Equipment Sheds	6-57
6.19.1 Site History	6-57
6.19.2 Geophysical Survey	6-57
6.19.3 Test Pit Excavation	6-58
6.19.4 Drilling	6-58
6.19.5 Analytical Results	6-58
6.19.5.1 Soil Samples	6-59
6.19.5.2 Groundwater Samples	6-60
6.20 Site 20 - Imhoff Tank	6-60
6.20.1 Site History	6-60
6.20.2 Soil Sampling	6-61
6.20.3 Analytical Results - Soil Samples	6-61
6.21 Site 21- Oiled Roads	6-61
6.21.1 Site History	6-61
6.21.2 Soil Sampling	6-62
6.21.3 Field Screening	6-62
6.21.4 Analytical Results - Soil Samples	6-63
6.22 Site 22 - Small Arms Range	6-63
6.22.1 Site History	6-63
6.22.2 Geophysical Survey	6-64
6.22.3 Soil Sampling	6-64
6.22.4 Analytical Results - Soil Samples	6-64
6.23 Site 23 - Septic Tanks	6-64
6.23.1 Site 23A - Firehouse Septic Tank	6-65

TABLE OF CONTENTS (continued)

Section	Page
6.23.1.1	Geophysical Survey 6-65
6.23.1.2	Drilling 6-65
6.23.1.3	Analytical Results 6-65
6.23.2	Site 23B – Instrument Laboratory Septic Tanks 6-66
6.23.2.1	Geophysical Survey 6-66
6.23.2.2	Soil Gas Survey 6-67
6.23.2.3	Drilling 6-67
6.23.2.4	Analytical Results – Soil Samples 6-67
6.23.3	Site 23 C – Residence Septic Tank #1 6-68
6.23.3.1	Geophysical Survey 6-68
6.23.4	Site 23 D – Residence Septic Tank #2 6-68
6.23.4.1	Geophysical Survey 6-68
6.23.4.2	Test Pit Excavation 6-68
6.23.5	Site 23 E – Building 4003 Septic Tank 6-68
6.23.5.1	Geophysical Survey 6-68
6.23.5.2	Test Pit Excavation 6-68
6.24	Site 25 – Main Leach Field 6-69
6.24.1	Site History 6-69
6.24.2	Geophysical Survey 6-69
6.24.3	Soil Gas Survey 6-70
6.24.4	Drilling 6-70
6.24.5	Analytical Results – Soil Samples 6-70
6.25	Remote Camera Site B 1 6-71
6.25.1	Site History 6-71
6.25.2	Geophysical Survey 6-71
6.25.3	Test Pit Excavation 6-71
6.25.4	Analytical Results – Soil Samples 6-71
7	HUMAN HEALTH RISK SCREENING
7.1	Conceptual Exposure Model 7-2
7.2	Procedures 7-3
7.2.1	Data 7-3
7.2.1.1	Total Combined Risk Data Set 7-3
7.2.1.2	Incremental Risk Data Set 7-4

TABLE OF CONTENTS (continued)

Section	Page
7.2.2 Screening Procedures	7-4
7.2.3 Cal-Modified PRGs	7-5
7.2.4 Calculation/Assignment of PRGs for Radionuclides	7-6
7.2.5 Calculation/Assignment of PRGs for Cobalt	7-6
7.2.6 Calculation/Assignment of PRGs for 2-Hexanone	7-7
7.2.7 Calculation/Assignment of PRGs for Other Compounds	7-7
7.3 Results	7-8
7.3.1 Total Combined Risk	7-8
7.3.2 Incremental Risk	7-8
8 CONCLUSIONS AND RECOMMENDATIONS	
8.1 Site 1 - Taxiway Landfill	8-3
8.1.1 Feature Location and Delineation	8-3
8.1.2 Contaminant Characterization	8-3
8.1.3 Risk Screening Results	8-4
8.1.4 Recommendations	8-4
8.2 Site 4 - Shoreline Disposal Area	8-4
8.2.1 Feature Location and Delineation	8-4
8.2.2 Contaminant Characterization	8-5
8.2.3 Risk Screening Results	8-5
8.2.4 Recommendations	8-6
8.3 Site 6 - Building 4033 - Instrument Laboratory Leach Line	8-6
8.3.1 Feature Location and Delineation	8-6
8.3.2 Contaminant Characterization	8-6
8.3.3 Risk Screening Results	8-6
8.3.4 Recommendations	8-7
8.4 Site 7 - Building 4070 - Dog Site Leach Field	8-7
8.4.1 Feature Location and Delineation	8-7
8.4.2 Contaminant Characterization	8-7
8.4.3 Risk Screening Results	8-7
8.4.4 Recommendations	8-7

TABLE OF CONTENTS (continued)

Section		Page
8.5	Site 8 - Building 4055 - Grease Pit.....	8-8
	85.1 Feature Location and Delineation	8-8
	8.5.2 Contaminant Characterization	8-8
	8.5.3 Risk Screening Results	8-8
	8.5.4 Recommendations	8-8
8.6	Site 9 - Buildings 4026, 4027, and 4070 - Radiological Survey	8-8
	8.6.1 Contaminant Characterization	8-9
	8.6.2 Recommendations	8-9
8.7	Site 10 - SSTB Target Range	8-9
	8.7.1 Historical Background	8-9
	8.7.2 Feature Location and Delineation	8-10
	8.7.3 Contaminant Characterization	8-10
	8.7.4 Risk Screening Results	8-11
	8.7.5 Recommendations	8-11
8.8	Site 11 - Building 4033 Landfill	8-11
	8.8.1 Feature Location and Delineation	8-12
	8.8.2 Contaminant Characterization	8-12
	8.8.3 Risk Screening Results	8-13
	8.8.4 Recommendations	8-13
8.9	Site 12 -East-West Runway Landfill	8-13
	8.9.1 Feature Location and Delineation	8-14
	8.9.1.1 Site 12A	8-14
	8.9.1.2 Site 12B and 12C	8-14
	8.9.1.3 Site 12D	8-14
	8.9.2 Contaminant Characterization - Sites 12B and 12C..	8-14
	8.9.3 Risk Screening Results	8-15
	8.9.4 Recommendations	8-15
8.10	Site 13 - Gully Landfill	8-15
	8.10.1 Feature Location and Delineation	8-15
	8.10.2 Contaminant Characterization	8-16
	8.10.3 Risk Screening Results	8-16
	8.10.4 Recommendations	8-17

TABLE OF CONTENTS (continued)

Section	Page
8.11 Site 14 – Warehouse Landfill	8-17
8.11.1 Feature Location and Delineation	8-17
8.11.2 Contaminant Characterization	8-17
8.11.3 Risk Screening Results	8-18
8.11.4 Recommendations	8-18
8.12 Site 15 – Building 4049 – Paint Shop	8-18
8.12.1 Feature Location and Delineation	8-18
8.12.2 Contaminant Characterization	8-18
8.12.3 Risk Screening Results	8-18
8.12.4 Recommendations	8-19
8.13 Site 16 – Building 4009 – Paint Storage	8-19
8.13.1 Feature Location and Delineation	8-19
8.13.2 Contaminant Characterization	8-19
8.13.3 Risk Screening Results	8-20
8.13.4 Recommendations	8-20
8.14 Site 17 – Old Building 5 – Vehicle Maintenance Area	8-20
8.14.1 Feature Location and Delineation	8-20
8.14.2 Contaminant Characterization	8-20
8.14.3 Risk Screening Results	8-21
8.14.4 Recommendations	8-21
8.15 Site 18 – Old Buildings 3 and 4 - Shops	8-21
8.15.1 Feature Location and Delineation	8-21
8.15.2 Contaminant Characterization	8-22
8.15.3 Risk Screening Results	8-22
8.15.4 Recommendations	8-22
8.16 Site 19 – Buildings 4006, 4007, 4008, 4050 – Equipment Sheds..	8-22
8.16.1 Feature Location and Delineation	8-22
8.16.2 Contaminant Characterization	8-22
8.16.3 Risk Screening Results	8-23
8.16.4 Recommendations	8-23
8.17 Site 20 – Imhoff Tank	8-23
8.17.1 Feature Location and Delineation	8-23
8.17.2 Contaminant Characterization	8-23
8.17.3 Risk Screening Results	8-24
8.17.4 Recommendations	8-24

TABLE OF CONTENTS (continued)

Section	Page
8.18 Site 21 – Oiled Roads	8-24
8.18.1 Feature Location and Delineation	8-24
8.18.2 Contaminant Characterization	8-24
8.18.3 Risk Screening Results	8-25
8.18.4 Recommendations	8-25
8.19 Site 22 – Small Arms Range	8-25
8.19.1 Feature Location and Delineation	8-25
8.19.1 Contaminant Characterization	8-25
8.19.2 Risk Screening Results	8-26
8.19.3 Recommendations	8-26
8.20 Site 23 – Septic Tanks	8-26
8.20.1 Site 23A – Firehouse Septic Tank	8-26
8.20.1.1 Feature Location and Delineation	8-26
8.20.1.2 Contaminant Characterization	8-27
8.20.1.3 Risk Screening Results..	8-27
8.20.1.4 Recommendations	8-27
8.20.2 Site 23B – Instrument Laboratory Septic Tanks	8-27
8.20.2.1 Feature Location and Delineation	8-27
8.20.2.2 Contaminant Characterization	8-27
8.20.2.3 Risk Screening Results	8-28
8.20.2.4 Recommendations	8-28
8.20.3 Site 23C – Residence Septic Tank #1	8-28
8.20.3.1 Feature Location and Delineation	8-28
8.20.3.2 Recommendations	8-28
8.20.4 Site 23D – Residence Septic Tank #2	8-28
8.20.4.1 Feature Location and Delineation	8-28
8.20.4.2 Recommendations	8-29
8.20.5 Site 23E – Building 4003 Septic Tank	8-29
8.20.5.1 Feature Location and Delineation	8-29
8.20.5.2 Recommendations	8-29

TABLE OF CONTENTS (continued)

Section	Page
8.2 1 Site 25 - Main Leach Field..	8-29
8.2 1.1 Feature Location and Delineation	8-29
8.2 1.2 Contaminant Characterization	8-30
8.2.1.3 Risk Screening Results	8-30
8.2 1.4 Recommendations	8-30
8.22 Remote Camera Site B 1	8-30
8.22.1 Feature Location and Delineation	8-30
8.22.2 Contaminant Characterization	8-30
8.22.3 Risk Screening Results	8-31
8.22.4 Recommendations	8-31

9 REFERENCES

TABLE OF CONTENTS (continued)

VOLUME 2

FIGURES

Figure	
2-1	Site Vicinity Map
2-2	Site Locations
2-3	Field Investigation Summary Dike Area Detail
2-4	Offsite Fuel Storage Tank Locations
2-5	Onsite Fuel Storage Tank Locations
2-6	Fuel Storage Tank Locations, Dike Area
3-1	Generalized Geologic Map of Imperial Valley Region
3-2	Average Sea Level and Salinity for the Salton Sea
4-1	Data Quality Objectives Decision Flow Diagram for Metals and Radionuclides
5-1	Input Parameters Used in Bouwer-Rice Equation
6-1	Geologic Cross Section Location Map
6-2	Geologic Cross Sections
6-3	Geologic Cross Sections, Dike Area
6-4	Geologic Cross Sections, Sites 1, 15, and 25
6-5	Geologic Cross Sections, Sites 6,7,13, and 23
6-6	Potentiometric Contour Map, May 1994
6-7	Potentiometric Contour Map, May 1994
6-8	Background Sediment and Surface Water Sampling Locations
6-9	Air Sampling Locations
6-10	Field Investigation Summary, Site 1 – Taxiway Landfill

TABLE OF CONTENTS (continued)

Figure

- 6-11 Field Investigation Summary, Site 4 – Shoreline Disposal Area
- 6-12 Field Investigation Summary, Sites 6 – Instrument Laboratory Leach Field and 23B – Instrument Laboratory Septic Tank
- 6-13 Field Investigation Summary, Site 7 – Dog Site Leach Field
- 6-14 Field Investigation Summary, Sites 8, 18, and 23E – Grease Pit, Shops, Septic Tank
- 6-15 Site 9 Radiological Background Stations
- 6-16 Site 9 Radiological Background Sampling Locations – Building 4025
- 6-17 Site 9 Radiological Sampling Locations – Building 4070
- 6-18 Site 9 Radiological Sampling Locations – Building 4026
- 6-19 Site 9 Radiological Sampling Locations – Building 4027
- 6-20 Field Investigation Summary, Site 10MB – Marine Target
- 6-21 Field Investigation Summary, Site 11 – Building 4033 Landfill
- 6-22 Field Investigation Summary, Site 12A – East-West Runway Landfill
- 6-23 Field Investigation Summary, Sites 12B and 12C – East-West Runway Landfill
- 6-24 Field Investigation Summary, Site 13 – Gully Landfill
- 6-25 Field Investigation Summary, Site 14 -Warehouse Landfill
- 6-26 Field Investigation Summary, Site 15 – Paint Shop
- 6-27 Field Investigation Summary, Site 16 – Paint Storage Building 4009
- 6-28 Field Investigation Summary, Site 17 – Vehicle Maintenance Old Building 5
- 6-29 Field Investigation Summary, Site 19 – Equipment Buildings 4006-4008,4050
- 6-30 Field Investigation Summary, Site 20 – Imhoff Tank
- 6-31 Schematic of Typical Imhoff Tank, Site 20 - Imhoff Tank

TABLE OF CONTENTS (continued)

Figure

- 6-32 Field Investigation Summary, Site 21 - Oiled Roads
- 6-33 Field Investigation Summary, Site 22 - Old Small Arms Range
- 6-34 Field Investigation Summary, Site 23A - Firehouse Septic Tank
- 6-35 Field Investigation Summary, Sites 23C and 23D - Residence Septic Tanks
- 6-36 Field Investigation Summary, Site 25 - Main Leach Field
- 6-37 Field Investigation Summary, Remote Camera Site B-1
- 7-1 Conceptual Exposure Model

TABLES

Table

- 2-1 Summary of Aerial Photographs Reviewed (Tables) for SSTB as of January 14, 1994
- 2-2 SSTB Tank Summary
- 3-1 Average Monthly Temperature, Rainfall, and Evaporation
- 3-2 Construction, Hydraulic Parameters, and Water Quality Analyses, USGS Wells LCRP 19 and LCRP 19A
- 3-3 Water Quality Analyses of the Salton Sea
- 4-1 Summary of Site Inspection Field Investigation (Tables)
- 4-2 Summary of Site Inspection Analyses Performed
- 5-1 Sample Container Types, Preservatives, and Holding Times
- 5-2 Monitoring Well Construction
- 5-3 Calculated Hydraulic Conductivities
- 5-4 Sample Station and Analytical Sample-Type Identifiers
- 5-5 Analytical Sample Site Identification Codes

TABLE OF CONTENTS (continued)

Table

- 5-6 Standard Analytical Detection Limits for Soil and Sediment Samples
- 5-7 Standard Analytical Detection Limits for Water Samples
- 5-8 Summary - Elevated Analytical Detection Limits
- 5-9 Field Duplicate Results
- 5-10 Analytes Detected in Rinsate Blanks
- 5-11 Compounds Detected in Trip Blanks
- 5-12 Summary of Geotechnical Analyses
- 6-1 Groundwater Elevation Measurements, April through August 1994
- 6-2 Summary of General Groundwater Chemistry Analytical Results
- 6-3 Analytes Detected in Soil Background Data
- 6-4 Analytes Detected in Groundwater Background Data
- 6-5 Analytes Detected in Sediment Background Data
- 6-6 Analytes Detected in Surface Water Background Locations
- 6-7 Comparison of Metals Concentrations in SSTB Soils with Representative Regional and Worldwide Abundances
- 6-8 Summary - Calculated Upper Tolerance Limits for Each Sample Matrix
- 6-9 Metals Results Exceeding Background UTLs for Soil
- 6-10 Radionuclides Results Exceeding Background UTLs for Soil
- 6-11 Metals Results Exceeding Background UTLs for Groundwater
- 6-12 Metals Results Exceeding Background UTLs for Sediment
- 6-13 Radionuclide Results Exceeding Background UTLs for Sediment
- 6-14 Metals Results Exceeding Background UTLs for Surface Water

TABLE OF CONTENTS (continued)

Table

- 6-15 Radionuclide Results Exceeding Background UTLs for Surface Water
- 6-16 Summary of Metals and Radionuclides Exceeding Background Upper Tolerance Limits
- 6-17 Air Monitoring Results - Asbestos
- 6-18 Air Monitoring Results - Metals
- 6-19 Analytes Detected in Soil, Site 1 - Taxiway Landfill
- 6-20 Analytes Detected in Groundwater, Site 1 - Taxiway Landfill
- 6-21 Analytes Detected in Soil, Site 4 - Shoreline Disposal Area
- 6-22 Analytes Detected in Sediment, Site 4 - Shoreline Disposal Area
- 6-23 Analytes Detected in Surface Water, Site 4 - Shoreline Disposal Area
- 6-24 Analytes Detected in Soil, Site 6 - Instrument Laboratory Leach Line
- 6-25 Analytes Detected in Soil, Site 7 - Dog Site Leach Field
- 6-26 Analytes Detected in Soil, Site 8 - Building 4055 Grease Pit
- 6-27 Analytes Detected in Groundwater, Site 8 - Building 4055 Grease Pit
- 6-28 Site 9 Background Radiological Exposure Rate Measurements
- 6-29 Building 4025 Background Radiological Exposure Rate Measurement
- 6-30 Site 9 Radiological Exposure Rate Measurements
- 6-31 Site 9 Direct Radiological Surface Contamination Measurements
- 6-32 Site 9 Transferable Radiological Surface Contamination Measurements
- 6-33 Analytes Detected in Sediment, Site 10 - Water Target
- 6-34 Analytes Detected in Surface Water, Site 10 - SSTB Range
- 6-35 Analytes Detected in Soil, Site 11 - Building 4033 Landfill
- 6-36 Analytes Detected in Sediment, Site 12 - East-West Runway Landfill

TABLE OF CONTENTS (continued)

Table

- 6-37 Analytes Detected in Surface Water, Site 12 - East-West Runway Landfill
- 6-38 Analytes Detected in Soil, Site 13 - Gully Landfill
- 6-39 Analytes Detected in Groundwater, Site 13 - Gully Landfill
- 6-40 Analytes Detected in Soil, Site 14 -Warehouse Landfill
- 6-41 Analytes Detected in Groundwater, Site 14 -Warehouse Landfill
- 6-42 Analytes Detected in Soil, Site 15 - Paint Shop Building 4049
- 6-43 Analytes Detected in Groundwater, Site 15 - Paint Shop Building 4049
- 6-44 Analytes Detected in Soil, Site 16 - Paint Storage Building 4009
- 6-45 Analytes Detected in Groundwater, Site 16 - Paint Storage Building 4009
- 6-46 Analytes Detected in Soil, Site 17 - Vehicle Maintenance Old Building 5
- 6-47 Analytes Detected in Groundwater, Site 17 - Vehicle Maintenance Building Old Building 5
- 6-48 Analytes Detected in Soil, Site 18 - Old Shop Buildings 3 and 4
- 6-49 Analytes Detected in Groundwater, Site 18 - Old Shop Buildings 3 and 4
- 6-50 Analytes Detected in Soil, Site 19 - Equipment Shed Buildings 4006, 4007, 4008, and 4050
- 6-51 Analytes Detected in Groundwater Site 19 -Equipment Shed Buildings 4006, 4007, 4008, and 4050
- 6-52 Analytes Detected in Soil, Site 20 - Imhoff Tank and Old Pump Station
- 6-53 Analytes Detected in Soil, Site 21- Oiled Roads
- 6-54 Analytes Detected in Soil, Site 22 - Old Small Arms Range
- 6-55 Analytes Detected in Soil, Site 23A - Firehouse Septic Tank
- 6-56 Analytes Detected in Groundwater, Site 23A - Firehouse Septic Tank

TABLE OF CONTENTS (continued)

Table

- 6-57 Analytes Detected in Soil, Site 23B – Septic Tanks and Leach Line
- 6-58 Analytes Detected in Soil, Site 25 – Main Leach Field
- 6-59 Analytes Detected in Soil, Remote Camera Site B-1
- 7-1 Summary of Total Combined Risk Estimates – Chronic Noncancer Hazard and Lifetime Cancer Risk
- 7-2 Summary of Dominant Risk Drivers – Total Combined Risk
- 7-3 Summary of Incremental Risk Estimates – Chronic Noncancer Hazard and Lifetime Cancer Risk

APPENDICES

A HISTORICAL DRAWINGS

B COMMON USES OF CHEMICALS OF POTENTIAL CONCERN

C MGC GEOPHYSICAL SURVEY FIGURES

TABLE OF CONTENTS (continued)

VOLUME 3

APPENDICES

- D SOIL GAS SURVEY DATA**
- E BOREHOLE LOGS**
- F TEST PIT LOGS**
- G MONITORING WELL CONSTRUCTION DETAILS**
- H WELL DEVELOPMENT LOGS**
- I WELL SAMPLING RECORDS**
- J SLUG TEST PLOTS**
- K VIBROCORE LOGS**
- L HAZARDOUS WORK PERMITS**
- M CHAIN-OF-CUSTODY FORMS**
- N ANALYTICAL DATA**

TABLE OF CONTENTS (continued)

VOLUME 4

APPENDICES

- 0 DATA VALIDATION REPORTS**
- P IDENTIFICATION OF LABORATORY CONTAMINANTS**
- Q GEOTECHNICAL LABORATORY DATA**
- R HYDROGRAPHS**
- S UPPER TOLERANCE LIMIT (UTL) CALCULATIONS**
- T AIR SAMPLING LABORATORY DATA**
- U RADIOLOGICAL INSTRUMENTATION CALIBRATION CERTIFICATES**
- V DRAFT U.S. EPA METHOD 4020 FOR PCB SOIL SCREENING**
- W RISK SCREENING - INPUT VARIABLES**
- X RISK SCREENING CALCULATIONS - TOTAL COMBINED RISK**
- Y RISK SCREENING CALCULATIONS - INCREMENTAL RISK**

TABLE OF CONTENTS (continued)

VOLUME 5

APPENDICES

- Z TECHNICAL MEMORANDUM BACKGROUND CHARACTERIZATION FOR METALS IN SOIL**

- AA RESPONSES TO REGULATORY AND COMMUNITY REVIEW**

TABLE OF CONTENTS

Section	Page
1 INTRODUCTION	
1.1 Purpose.....	1-1
1.2 Background.....	1-1
1.3 Scope.....	1-1
1.3.1 Comparison of Statistical Methods.....	1-1
1.3.2 Comparison of Different Background Sample Data Sets.....	1-2
2 IDENTIFICATION OF BACKGROUND DATA SETS	
2.1 Background Sample Data Set.....	2-1
2.1.1 Background Samples from all Depths.....	2-1
2.1.2 Background Samples from Depths Less than 25 Feet.....	2-1
2.2 Combined Background and Site Data Set.....	2-1
3 CALCULATION OF BACKGROUND CONCENTRATIONS	
3.1 Identification of Distribution of Background Populations.....	3-1
3.2 Upper Tolerance Limit (UTL).....	3-1
3.3 95th Percentile.....	3-1
3.4 95th Quantile.....	3-2
3.5 Uncertainties in Application of Background Threshold Concentrations.....	3-3
4 COMPARATIVE EVALUATION OF BACKGROUND CHARACTERIZATION METHODS	
4.1 Comparison of Background Concentration Calculation Methods.....	4-1
4.2 Comparison of Background Data Sets.....	4-1
4.2.1 Effects of Depth on Background Sample Population.....	4-1
4.2.2 Background Data Set Versus Combined Data Set.....	4-2
4.2.2.1 Arsenic.....	4-3
4.2.2.2 Beryllium.....	4-3
4.2.2.3 Chromium.....	4-3
4.3 Comparison with Regional Background Metal Concentrations.....	4-3

Table of Contents (continued)

Section	Page
5 SUMMARY AND CONCLUSIONS	
5.1 Comparison of Background Concentration Calculation Methods	5-1
5.2 Comparison of Background Data Sets	5-1

6 REFERENCES

ATTACHMENTS

Attachment

- A SITE INSPECTION DATA SET FOR METALS CONCENTRATIONS IN SOIL**
- B DISTRIBUTION PLOTS FOR METALS IN SOIL**
- C COMPARATIVE PLOTS FOR METALS IN SOIL**

FIGURES

Figure

- 2-1 Soil Sample Locations
- 2-2 Histogram Depicting Distribution of Background and Site Soil Sample Depths

- 4-1 Comparative Plot - Arsenic
- 4-2 Comparative Plot - Beryllium
- 4-3 Comparative Plot - Chromium

TABLES

Table

- 3-1 Calculated Background Concentrations for Metals in Soil