

STREAM INVENTORY REPORT

Unnamed Tributary to Bear River "A"

INTRODUCTION

A stream inventory was conducted during the summer of 1997 on an unnamed tributary to Bear River designated "A". The objective of the habitat inventory was to document the habitat available to anadromous salmonids in unnamed tributary A.

The objective of this report is to document the current habitat conditions, and recommend options for the potential enhancement of habitat for coho salmon and steelhead trout. Recommendations for habitat improvement activities are based upon target habitat values suitable for salmonids in California's north coast streams.

WATERSHED OVERVIEW

Unnamed tributary A is a tributary to Bear River, which drains to the Pacific Ocean. It is located in Humboldt County, California (Map 1). Unnamed tributary A's legal description at the confluence with Bear River is T01S R01E S22. Its location is 40.3658 degrees north latitude and 124.0558 degrees west longitude. Unnamed tributary A has 0.6 miles of blue line stream according to the USGS Bull Creek 7.5 minute quadrangle. Unnamed tributary A drains a watershed of approximately 0.2 square miles. Elevations range from about 1,580 feet at the mouth of the creek to 2,120 feet in the headwater areas. Redwood forest and mixed conifer forest dominate the watershed. The watershed is entirely privately owned and is managed for timber production. Vehicle access exists via Mattole Road to Pole Line Road.

METHODS

The habitat inventory conducted in unnamed tributary A follows the methodology presented in the *California Salmonid Stream Habitat Restoration Manual* (Flosi and Reynolds, 1991 rev. 1994). The California Conservation Corps (CCC) Technical Advisors and AmeriCorps Watershed Stewards Project (AmeriCorps WSP) Members who conducted the inventory were trained in standardized habitat inventory methods by the California Department of Fish and Game (DFG). This inventory was conducted by a two-person team.

SAMPLING STRATEGY

The inventory uses a method that samples approximately 10% of the habitat units within the survey reach (Hopelain, 1994). All habitat units included in the survey are classified according to habitat type and their lengths are measured. All pool units are measured for maximum depth, depth of pool tail crest, dominant substrate composing the pool tail crest, and embeddedness. Habitat unit types encountered for the first time are further measured for all the parameters and characteristics on the field form. Additionally, from the ten habitat units on each field form page, one is randomly selected for complete measurement.

Unnamed Tributary to Bear River A

HABITAT INVENTORY COMPONENTS

A standardized habitat inventory form has been developed for use in California stream surveys and can be found in the *California Salmonid Stream Habitat Restoration Manual*. This form was used in unnamed tributary A to record measurements and observations. There are nine components to the inventory form.

1. Flow:

Flow is measured in cubic feet per second (cfs) at the bottom of the stream survey reach using standard flow measuring equipment, if available. In some cases flows are estimated.

2. Channel Type:

Channel typing is conducted according to the classification system developed and revised by David Rosgen (1985 rev. 1994). This methodology is described in the *California Salmonid Stream Habitat Restoration Manual*. Channel typing is conducted simultaneously with habitat typing and follows a standard form to record measurements and observations. There are five measured parameters used to determine channel type: 1) water slope gradient, 2) entrenchment, 3) width/depth ratio, 4) substrate composition, and 5) sinuosity.

3. Temperatures:

Both water and air temperatures are measured and recorded at every tenth habitat unit. The time of the measurement is also recorded. Both temperatures are taken in degrees Fahrenheit at the middle of the habitat unit and within one foot of the water surface.

4. Habitat Type:

Habitat typing uses the 24 habitat classification types defined by McCain and others (1988). Habitat units are numbered sequentially and assigned a type identification number selected from a standard list of 24 habitat types. Dewatered units are labeled "dry". The unnamed tributary A habitat typing used standard basin level measurement criteria. These parameters require that the minimum length of a described habitat unit must be equal to or greater than the stream's mean wetted width. Channel dimensions were measured using hip chains, range finders, tape measures, and stadia rods. All units were measured for mean length; additionally, the first occurrence of each unit type and a randomly selected 10% subset of all units were sampled for all features on the sampling form. Pool tail crest depth at each pool unit was measured in the thalweg. All measurements were in feet to the nearest tenth.

5. Embeddedness:

The depth of embeddedness of the cobbles in pool tail-out reaches is measured by the percent of the cobble that is surrounded or buried by fine sediment. In unnamed tributary A, embeddedness was ocularly estimated. The values were recorded using the following ranges: 0 - 25% (value 1),

Unnamed Tributary to Bear River A

26 - 50% (value 2), 51 - 75% (value 3) and 76 - 100% (value 4). Additionally, a value of 5 was assigned to tail-outs deemed not suitable for spawning due to inappropriate substrate particle size, having a bedrock tail-out, or other considerations.

6. Shelter Rating:

Instream shelter is composed of those elements within a stream channel that provide salmonids protection from predation, reduce water velocities so fish can rest and conserve energy, and allow separation of territorial units to reduce density related competition. The shelter rating is calculated for each fully-described habitat unit by multiplying shelter value and percent cover. Using an overhead view, a quantitative estimate of the percentage of the habitat unit covered is made. All cover is then classified according to a list of nine cover types. In unnamed tributary A, a standard qualitative shelter value of 0 (none), 1 (low), 2 (medium), or 3 (high) was assigned according to the complexity of the cover. Thus, shelter ratings can range from 0-300 and are expressed as mean values by habitat types within a stream.

7. Substrate Composition:

Substrate composition ranges from silt/clay sized particles to boulders and bedrock elements. In all fully-described habitat units, dominant and sub-dominant substrate elements were ocularly estimated using a list of seven size classes and recorded as a one and two respectively. In addition the dominant substrate composing the pool tail outs is recorded for each pool.

8. Canopy:

Stream canopy density was estimated using modified handheld spherical densimeters as described in the *California Salmonid Stream Habitat Restoration Manual*. Canopy density relates to the amount of stream shaded from the sun. In unnamed tributary A, an estimate of the percentage of the habitat unit covered by canopy was made from the center of approximately every third unit in addition to every fully-described unit, giving an approximate 30% sub-sample. In addition, the area of canopy was estimated ocularly into percentages of coniferous or deciduous trees.

9. Bank Composition and Vegetation:

Bank composition elements range from bedrock to bare soil. However, the stream banks are usually covered with grass, brush, or trees. These factors influence the ability of stream banks to withstand winter flows. In unnamed tributary A, the dominant composition type and the dominant vegetation type of both the right and left banks for each fully-described unit were selected from the habitat inventory form. Additionally, the percent of each bank covered by vegetation was estimated and recorded.

Unnamed Tributary to Bear River A

DATA ANALYSIS

Data from the habitat inventory form are entered into Habitat, a dBASE 4.2 data entry program developed by Tim Curtis, Inland Fisheries Division, California Department of Fish and Game. This program processes and summarizes the data, and produces the following six tables:

- Riffle, flatwater, and pool habitat types
- Habitat types and measured parameters
- Pool types
- Maximum pool depths by habitat types
- Dominant substrates by habitat types
- Mean percent shelter by habitat types

Graphics are produced from the tables using Quattro Pro. Graphics developed for unnamed tributary A include:

- Riffle, flatwater, pool habitats by percent occurrence
- Riffle, flatwater, pool habitats by total length
- Total habitat types by percent occurrence
- Pool types by percent occurrence
- Total pools by maximum depths
- Embeddedness
- Pool cover by cover type
- Dominant substrate in the pool tail-outs
- Percent canopy
- Bank composition by composition type
- Bank vegetation by vegetation type

HABITAT INVENTORY RESULTS AND DISCUSSION

The habitat inventory of June 4, 1997 was conducted by David Jones and Bill Malinowski (CCC/AmeriCorps WSP). The total length of the stream surveyed was 707 feet.

Flow was measured at the bottom of the survey reach with a Marsh-McBirney Model 2000 flowmeter at 0.15 cfs on June 5, 1997.

Unnamed tributary A is an A3 channel type for the entire 707 feet of stream surveyed. This type of channel is a steep, narrow, cascading stream, with high energy and a high debris transport associated with depositional soils and a cobble channel. A3 channel types are generally not suitable for fish habitat improvement projects.

The water temperatures recorded on the survey day, June 4, 1997 ranged from 52 to 55 degrees Fahrenheit. Air temperatures ranged from 55 to 57 degrees Fahrenheit. This is a good water temperature range for salmonids, but water temperature data during the warm summer months are lacking. For a more complete and accurate water temperature profile, 24-hour temperatures need to be monitored throughout the warm summer months.

Unnamed Tributary to Bear River A

Based on the total length of this survey, Level II habitat units consisted of 74% flatwater units, 15% riffle units, and 12% pool units. The pools are relatively shallow, with all ten of the pools having a maximum depth less than two feet.

Two of the ten pool tail-outs measured had embeddedness ratings of 3 or 4. One had an embeddedness rating of 1. Cobble embeddedness of 25% or less, a rating of 1, is considered best for the needs of salmon and steelhead. In unnamed tributary A, sediment sources should be mapped and rated according to their potential sediment yields, and control measures should be taken.

The mean shelter rating for pools was moderate with a rating of 67. The shelter rating in the flatwater habitats was 80. A pool shelter rating of approximately 100 is desirable. Log and root wad cover structures in the pool and flatwater habitats are needed to improve both summer and winter salmonid habitat.

Three of the ten pool tail-outs measured had gravel or small cobble as the dominant substrate. This is generally considered limiting for spawning salmonids.

The mean percent canopy density for the stream was 92%. The percentage of right and left bank covered with vegetation was moderate at 58% and 49%, respectively.

RECOMMENDATIONS

- 1) Unnamed tributary A should be managed as an anadromous, natural production stream.
- 2) The limited water temperature available suggest that the maximum temperatures are within the acceptable range for juvenile salmonids. To establish more complete and meaningful temperature regime information, 24-hour monitoring during the July and August temperature extreme period should be performed for three to five years.

COMMENTS AND LANDMARKS

The following landmarks and possible problem sites were noted. All distances are approximate and taken from the beginning of the survey reach.

Position Comments:
(ft):

- | | |
|------|--|
| 0' | Start of survey at confluence with Bear River. Channel type is an A3. |
| 167' | Right bank tributary, it is not accessible to fish. The water temperature was 52 degrees Fahrenheit. |
| 707' | End of survey. One fish was observed in Habitat Unit #006. The channel is |

Unnamed Tributary to Bear River A

extremely entrenched. The flow drops off significantly after the tributary at 167'. Spawning habitat appears to be limited.

REFERENCES

Flosi, G., and F. Reynolds. 1994. California salmonid stream habitat restoration manual, 2nd edition. California Department of Fish and Game, Sacramento, California.

Hopelain, J. 1995. Sampling levels for fish habitat inventory, unpublished manuscript. California Department of Fish and Game, Inland Fisheries Division, Sacramento, California.

Unnamed Tributary to Bear River A

LEVEL III and LEVEL IV HABITAT TYPE KEY

HABITAT TYPE	LETTER	NUMBER
RIFFLE		
Low Gradient Riffle	[LGR]	1.1
High Gradient Riffle	[HGR]	1.2
CASCADE		
Cascade	[CAS]	2.1
Bedrock Sheet	[BRS]	2.2
FLATWATER		
Pocket Water	[POW]	3.1
Glide	[GLD]	3.2
Run	[RUN]	3.3
Step Run	[SRN]	3.4
Edgewater	[EDW]	3.5
MAIN CHANNEL POOLS		
Trench Pool	[TRP]	4.1
Mid-Channel Pool	[MCP]	4.2
Channel Confluence Pool	[CCP]	4.3
Step Pool	[STP]	4.4
SCOUR POOLS		
Corner Pool	[CRP]	5.1
Lateral Scour Pool - Log Enhanced	[LSL]	5.2
Lateral Scour Pool - Root Wad Enhanced	[LSR]	5.3
Lateral Scour Pool - Bedrock Formed	[LSBk]	5.4
Lateral Scour Pool - Boulder Formed	[LSBo]	5.5
Plunge Pool	[PLP]	5.6
BACKWATER POOLS		
Secondary Channel Pool	[SCP]	6.1
Backwater Pool - Boulder Formed	[BPB]	6.2
Backwater Pool - Root Wad Formed	[BPR]	6.3
Backwater Pool - Log Formed	[BPL]	6.4
Dammed Pool	[DPL]	6.5