

TABLE OF CONTENTS (continued)

VOLUME 2

FIGURES

Figure

- 2-1 Site Vicinity Map
- 2-2 Site Locations
- 2-3 Field Investigation Summary Dike Area Detail
- 3-1 Regional Geology
- 3-2 Average Sea Level and Salinity for the Salton Sea
- 5-1 Input Parameters Used in Bouwer-Rice Equation
- 6-1 Geologic Cross Section Location Map
- 6-2 Geologic Cross Sections
- 6-3 Geologic Cross Sections
- 6-4 Geologic Cross Sections
- 6-5 Geologic Cross Sections
- 6-6 Potentiometric Contour Map
- 6-7 Potentiometric Surface Map
- 6-8 Background Sediment and Surface Water Sampling Locations
- 6-9 Air Sampling Locations
- 6-10 Field Investigation Summary Map, Site 1 – Taxiway Landfill
- 6-11 Field Investigation Summary Map, Site 4 – Shoreline Disposal Area
- 6-12 Field Investigation Summary Map, Sites 6 – Instrument Laboratory Leach Field and 23B – Instrument Laboratory Septic Tank
- 6-13 Field Investigation Summary Map, Site 7 – Dog Site Leach Field

TABLE OF CONTENTS (continued)

Figure	
6-14	Field Investigation Summary Map, Sites 8, 18, and 23E – Grease Pit, Shops, Septic Tank
6-15	Radiological Background Stations
6-16	Radiological Background Sampling Locations – Building 4025
6-17	Radiological Sampling Locations – Building 4070
6-18	Radiological Sampling Locations – Building 4026
6-19	Radiological Sampling Locations – Building 4027
6-20	Field Investigation Summary, Site 10MB – Marine Target
6-21	Field Investigation Summary, Site 11 – Building 4033 Landfill
6-22	Field Investigation Summary, Site 12A – East-West Runway Landfill
6-23	Field Investigation Summary, Sites 12B and 12C – East-West Runway Landfill
6-24	Field Investigation Summary, Site 13 – Gully Landfill
6-25	Field Investigation Summary, Site 14 – Warehouse Landfill
6-26	Field Investigation Summary, Site 15 – Paint Shop
6-27	Field Investigation Summary, Site 16 – Paint Storage Building 4009
6-28	Field Investigation Summary, Site 17 – Vehicle Maintenance Old Building 5
6-29	Field Investigation Summary, Site 19 – Equipment Buildings 4006-4008, 4050
6-30	Field Investigation Summary, Site 20 – Imhoff Tank
6-31	Schematic of Typical Imhoff Tank
6-32	Field Investigation Summary, Site 21 – Oiled Roads
6-33	Field Investigation Summary, Site 22 – Old Small Arms Range
6-34	Field Investigation Summary, Site 23A – Firehouse Septic Tank
6-35	Field Investigation Summary, Sites 23C and 23D – Residence Septic Tanks

TABLE OF CONTENTS (continued)

Figure

- 6-36 Field Investigation Summary, Site 25 – Main Leach Field
- 6-37 Field Investigation Summary, Remote Camera Site B-1

TABLES

Table

- 2-1 Summary of Aerial Photographs Reviewed
- 3-1 Average Monthly Temperature, Rainfall, and Evaporation
- 3-2 Construction, Hydraulic Parameters, and Water Quality Analyses for USGS Wells LCRP 19 and LCRP 19A
- 3-3 Selected Water Quality Analyses of the Salton Sea
- 4-1 Summary of Site Inspection Field Investigation
- 4-2 Summary of Site Inspection Analyses Performed
- 5-1 Monitoring Well Construction Salton Sea Test Base
- 5-2 Calculated Hydraulic Conductivities
- 5-3 Sample Station and Analytical Sample-Type Identifiers
- 5-4 Analytical Sample Site Identification Codes
- 5-5 Summary of Geotechnical Analyses
- 5-6 Sample, Container Types, Preservatives, and Holding Times
- 5-7 Field Duplicate Results
- 5-8 Analytes Detected in Rinseate Blanks
- 5-9 Compounds Detected in Trip Blanks
- 6-1 Groundwater Elevation Measurements, April through August 1994
- 6-2 Summary of General Groundwater Chemistry Analytical Results

TABLE OF CONTENTS (continued)

Table

- 6-3 Analytes Detected in Soil Background Data
- 6-4 Analytes Detected in Groundwater Background Data
- 6-5 Analytes Detected in Sediment Background Data
- 6-6 Analytes Detected in Surface Water Background Locations
- 6-7 Metals Results Exceeding Background UTLs for Soils
- 6-8 Radionuclide Results Exceeding Background UTLs for Soils
- 6-9 Metals Results Exceeding Background UTLs for Groundwater
- 6-10 Metals Results Exceeding Background UTLs for Sediments
- 6-11 Radionuclide Results Exceeding Background UTLs for Sediment
- 6-12 Metals Results Exceeding Background UTLs for Surface Water
- 6-13 Radionuclide Results Exceeding Background UTLs for Surface Water
- 6-14 Summary of Metals and Radionuclides Exceeding Background UTLs
- 6-15 Air Monitoring Results – Asbestos
- 6-16 Air Monitoring Results – Metals
- 6-17 Analytes Detected in Soil, Site 1 – Taxiway Landfill
- 6-18 Analytes Detected in Groundwater, Site 1 – Taxiway Landfill
- 6-19 Analytes Detected in Soil, Site 4 – Shoreline Disposal Area
- 6-20 Analytes Detected in Sediment, Site 4 – Shoreline Disposal Area
- 6-21 Analytes Detected in Surface Water, Site 4 – Shoreline Disposal Area
- 6-22 Analytes Detected in Soil, Site 6 – Instrument Laboratory Leach Line
- 6-23 Analytes Detected in Soil, Site 7 – Dog Site Leach Field
- 6-24 Analytes Detected in Soil, Site 8 – Building 4055 Grease Pit

TABLE OF CONTENTS (continued)

Table	
6-25	Analytes Detected in Groundwater, Site 8 – Building 4055 Grease Pit
6-26	Site 9 Background Radiological Exposure Rate Measurements
6-27	Building 4025 Background Radiological Exposure Rate Measurements
6-28	Site 9 Radiological Exposure Rate Measurements
6-29	Site 9 Direct Radiological Surface Contamination Measurements
6-30	Site 9 Transferable Radiological Surface Contamination Measurements
6-31	Analytes Detected in Sediment, Site 10 – Water Target
6-32	Analytes Detected in Surface Water, Site 10 – SSTB
6-33	Analytes Detected in Soil, Site 11 – Building 4033 Landfill
6-34	Analytes Detected in Sediment, Site 12 – East-West Runway Landfill
6-35	Analytes Detected in Surface Water, Site 12 – East-West Runway Landfill
6-36	Analytes Detected in Soil, Site 13 – Gully Landfill
6-37	Analytes Detected in Groundwater, Site 13 – Gully Landfill
6-38	Analytes Detected in Soil, Site 14 – Warehouse Landfill
6-39	Analytes Detected in Groundwater, Site 14 – Warehouse Landfill
6-40	Analytes Detected in Soil, Site 15 – Paint Shop Building 4099
6-41	Analytes Detected in Groundwater, Site 15 – Paint Shop Building 4099
6-42	analytes Detected in Soil, Site 16 – Paint Storage Building 4009
6-43	Analytes Detected in Groundwater, Site 16 – Paint Storage Building 4009
6-44	Analytes Detected in Soil, Site 17 – Vehicle Maintenance Old Building 5
6-45	Analytes Detected in Groundwater, Site 17 – Vehicle Maintenance Building Old Building 5

TABLE OF CONTENTS (continued)

Table	
6-46	Analytes Detected in Soil, Site 18 – Old Shop Buildings 3 and 4
6-47	Analytes Detected in Groundwater, Site 18 – Old Shop Buildings 3 and 4
6-48	Analytes Detected in Soil, Site 19 – Equipment Shed Buildings 4006, 4007, 4008, and 4050
6-49	Analytes Detected in Groundwater Site 19 – Equipment Shed Buildings 4006, 4007, 4008, and 4050
6-50	Analytes Detected in Soil, Site 20 – Imhoff Tank and Old Pump Station
6-51	Analytes Detected in Soil, Site 21 – Oiled Roads
6-52	Analytes Detected in Soil, Site 22 – Old Small Arms Range
6-53	Analytes Detected in Soil, Site 23A – Firehouse Septic Tank
6-54	Analytes Detected in Groundwater, Site 23A – Firehouse Septic Tank
6-55	Analytes Detected in Soil, Site 23B – Septic Tanks and Leach Line
6-56	Analytes Detected in Soil, Site 25 – Main Leach Line
6-57	Analytes Detected in Soil, Remote Camera Site
7-1	Total Combined (Including Background) Risk – PRG Ratios and Dominant Risk Drivers, Residential Exposure, Carcinogenic Effects
7-2	Total Combined (Including Background) Risk – PRG Ratios and Dominant Risk Drivers, Residential Exposure, Noncarcinogenic Effects
7-3	Total Combined (Including Background) Risk – PRG Ratios and Dominant Risk Drivers, Industrial Exposure, Carcinogenic Effects
7-4	Total Combined (Including Background) Risk – PRG Ratios and Dominant Risk Drivers, Industrial Exposure, Noncarcinogenic Effects
7-5	Total Combined (Including Background) Risk – PEA Risk Estimates and Dominant Risk Drivers, Residential Exposure, Carcinogenic Effects

TABLE OF CONTENTS (continued)

Table

- 7-6 Total Combined (Including Background) Risk – PEA Risk Estimates and Dominant Risk Drivers, Residential Exposure, Noncarcinogenic Effects
- 7-7 Incremental (Nonbackground) Risk – PRG Ratios and Dominant Risk Drivers, Residential Exposure, Carcinogenic Effects
- 7-8 Incremental (Nonbackground) Risk – PRG Ratios and Dominant Risk Drivers, Residential Exposure, Noncarcinogenic Effects
- 7-9 Incremental (Nonbackground) Risk – PRG Ratios and Dominant Risk Drivers, Industrial Exposure, Carcinogenic Effects
- 7-10 Incremental (Nonbackground) Risk – PRG Ratios and Dominant Risk Drivers, Industrial Exposure, Noncarcinogenic Effects
- 7-11 Incremental (Nonbackground) Risk – PEA Risk Estimates and Dominant Risk Drivers, Residential Exposure, Carcinogenic Effects
- 7-12 Incremental (Nonbackground) Risk – PEA Risk Estimates and Dominant Risk Drivers, Residential Exposure, Noncarcinogenic Effects

APPENDICES

A HISTORICAL DRAWINGS

B MGC GEOPHYSICAL SURVEY FIGURES