

Date \_\_\_\_\_  
90457 6-63 PM SPO

Locality \_\_\_\_\_

Subject \_\_\_\_\_

Highland Lake 7/14/77  
Saddle Northside

7' x 18" = 20 SACKS ALL GUT

Crest South of Well by

BM RACK 12' x 18"

= 25-30 SACKS

MISC LOOSE ROCKS 5 SACKS

RT 3 yr classes

76 plant 5-6" abundant

75 " 8-9" "

74 " 12" sparse

Recl plant every 3rd

yr good condition

Outflow 1/3 Lts

Notes made by \_\_\_\_\_

RT 9.5 9.5, 9.0

Lang RAH

1 muna

Gill net 4 hrs

10.2 5.8, 6.0 4.2

Valve closed to  $\frac{1}{2}$  cfs

Apply mortar & rock on crest  
of dam

Written Up.

Buck Island

6 BN 12-14 "

Lang RAH

7/15/76

Date \_\_\_\_\_

90457 6-63 5M SPO

Locality \_\_\_\_\_

Subject \_\_\_\_\_